

439.

## AI Industries Model V14 simulator – universal joint yoke pin cracking

Inspection bodies and controllers are asked to be aware that cracking has been detected during the routine annual inspection of a universal joint yoke pin from an AI Industries Model V14 simulator. The device was manufactured in 2002. Inspection bodies should ensure that these components are included on the NDT schedule.



Committee Members: Mr. D Dadswell (Chairman), Mr. A Mellor (Secretary), Mr. P Smith, Mr. J Green,  
Mr. D Cox, Mr. I Davies, Mr. J Shilling & Mr. D Inman

[www.naflic.co.uk](http://www.naflic.co.uk)

Supported By:

